

Test report **18-TA4703**

Article: Surface Metal
White, RAL 9002SA
Secura

Test requested by: Secura Sweden AB
Rickard Dahlstedt

Tests are carried out according to standard: **Requirements according to Möbelfakta category 1 and 2**
EN 12720:2009+A1:2013, SIS 839117:1993 and EN ISO 105-E04:1996

Discrepancies: None

Result and observations: The sample submitted for test fulfils the requirements in above mentioned standards.

Measurement: Detailed information on measurement uncertainty can be obtained from Kinnarps Test and Verification Center on request.

Report: This report relates to sample submitted for test and no other. The report may not be reproduced other than in full, except with the prior written approval of the issuing laboratory.

Kinnarp 24th of August 2018



Approved by Daniel Landberg
Manager Kinnarps Test- & verification Center



Tested by Susanne Norling
Test technician

Item description:		
Date of manufacture:	18/6 2018	
Date of arrival:	18/6 2018	
Date of test:	13-15/8 2018	
Material	White coated metal, RAL 9002SA	
Remarks, comments:	This test report comprise requirements according to Möbelfakta, Contract and office environments	
	cat 1 Storage - insides, drawers bottoms ,leg	
	cat 2 Storage - outside surfaces	
Test conditions:		
Conditioning atmosphere	(50 ± 5)% RH (23 ± 2)° C	Within limit during test
Laboratory atmosphere	(20 ± 5)° C	Within limit during test

Test and method		Requirements	Test results	Pass/Fail or N/A
Category 1	EN 12720: 2009 +A1:2013		<i>(Scale 1-5, if not otherwise stated)</i>	
Water	6 h	≥ 4	5	Pass
Paraffin oil	24 h	≥ 4	5	Pass
Category 2	EN 12720: 2009 +A1:2013		<i>(Scale 1-5, if not otherwise stated)</i>	
Water	16 h	≥ 4	5	Pass
Paraffin oil	24 h	≥ 4	5	Pass
Coffee Nes café original light dark, recipe acc. to standard.	1 h *	≥ 4	5	Pass
Scratch 3 N	SIS 839117:1973	scratch width ≤ 0,5mm, no perforation	<0,5mm	Pass
	EN ISO 105-E04			
Sweat pH 5,5 armrests only	1 h **	≥ 4	-	N/A
Sweat pH 8 armrests only	1 h **	≥ 4	-	N/A

Comments:

- * = Storage, outside horizontal surfaces ≤ 1250mm above floor
- ** = Armrest
- *** = Door and drawer fronts

End of report